

HEAVY DUTY TIRE, LLC

RECONDITION PROCESS

STEP 1

INSPECTION

- No Major Cuts Or Punctures in Tread
- No Sidewall Cuts Or Punctures
- Wheel Is Free of Rust & Cracks

STEP 2

TREAD DEPTH MEASUREMENT

- Tread Depth Measurement Must Have 90% Remaining Tread or More

STEP 3

PAINT PROCESS

- All Tires Are Painted With A Black Tire Paint To Look Good As New
- It Also Protects the Tires from premature Aging From UV Light

STEP 4

WHEEL REFINISHING

- Wheels Are Painted To The Original Equipment Color Or Any Color Specified

STEP 5

COMPLETED RECONDITIONING PROCESS

Benefits of the Recycling Process:

- Ready To Go Assembly
- Eliminating Down Time and Lost Revenue
- Same Day Shipping



READY TO GO ASSEMBLIES FOR:

LOADERS – SKID STEERS – TELEHANDLERS BOOM LIFTS – FORKLIFTS – SCISSOR LIFTS

VISIT OUR WEBSITE AT WWW.HEAVYDUTYTIRES.COM

NEXT TIME YOU NEED TIRES CALL US FIRST !

844-HD-TIRES (844-438-4737)